

Explorer

User guide

Charging:

Take the torch with one hand and turn the other hand at speed ca. 2.5 - 3 revs per sec.

The torch:

Press the button on the torch - it shines Ix LED, press the button again - it shines 3x LED, another pressing - 3x LED blinking, another pressing - the torch is off.

Using as a headlamp:

Fasten the torch into the holder and set the straps so the torch would hold on your head.

Main Technical parameters:

- Maximal luminosity: 45000Mcd
- Shining time after 1 minute of charging (3 x LED) >40min.
- Shining time after 1 minute of charging (1 x LED): >90min.
- Blinking time after 1 minute of charging (3 x LED) : >90min.
- Blinking frequency: 2Hz